

EAST Search History

103

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	503	(156/73.5).CCLS.	US-PGPUB; USPAT	OR	OFF	2006/05/23 09:00
L2	368	(228/2.1).CCLS.	US-PGPUB; USPAT	OR	OFF	2006/05/23 09:00
L3	616	(228/112.1).CCLS.	US-PGPUB; USPAT	OR	OFF	2006/05/23 09:47
L4	2553	((427/446) or (427/449) or (427/453) or (427/450) or (427/451) or (427/447) or (427/455) or (427/456) or (228/112.1)).CCLS.	US-PGPUB; USPAT	OR	OFF	2006/05/23 09:01
L5	0	4 and @pd>"200501229"	US-PGPUB; USPAT	OR	ON	2006/05/23 09:01
L6	79	4 and @pd>"20051229"	US-PGPUB; USPAT	OR	ON	2006/05/23 09:01
L7	44	6 and (weld or welded or welding)	US-PGPUB; USPAT	OR	ON	2006/05/23 09:05
L8	20347	(thermal or flame or plasma or arc or hvoft) near4 (spray or sprayed or spraying)	US-PGPUB; USPAT	OR	ON	2006/05/23 09:42
L9	1	8 and 1	US-PGPUB; USPAT	OR	ON	2006/05/23 09:07
L10	6	8 and 2	US-PGPUB; USPAT	OR	ON	2006/05/23 09:09
L11	12	8 and 3	US-PGPUB; USPAT	OR	ON	2006/05/23 09:09
L12	6	11 not 10	US-PGPUB; USPAT	OR	ON	2006/05/23 09:13
L13	4386	(friction near3 welding)	US-PGPUB; USPAT	OR	ON	2006/05/23 09:47
L14	113	13 and 8	US-PGPUB; USPAT	OR	ON	2006/05/23 09:13
L15	18000	(thermal or flame or plasma or arc or hvoft) near4 (spray or sprayed or spraying)	EPO; JPO; DERWENT	OR	ON	2006/05/23 09:35
L16	4547	(friction near3 welding)	EPO; JPO; DERWENT	OR	ON	2006/05/23 09:35
L17	7	15 and 16	EPO; JPO; DERWENT	OR	ON	2006/05/23 09:35
L18	1264	(thermal or flame or plasma or arc or hvoft) near4 (spray or sprayed or spraying).clm.	US-PGPUB	OR	ON	2006/05/23 09:42
L19	440	(friction near3 welding).clm.	US-PGPUB	OR	ON	2006/05/23 09:42
L20	12	18 and 19	US-PGPUB	OR	ON	2006/05/23 09:42

EAST Search History

L21	203	(427/454).CCLS.	US-PGPUB; USPAT	OR	OFF	2006/05/23 09:47
L22	0	13 and 21	US-PGPUB; USPAT	OR	ON	2006/05/23 09:47